

Components



- [14. Pistons for High-Power engines.](#)
- [15. Valve-Spring problems and their solution.](#)
- [16. Sparking-plug Problems and their solution.](#)
- [17. Exhaust Valve Problems and their solutions.](#)
- [18. Bearings Development.](#)
- [25B. Inverted-cup tappets.](#)
- [28. Fabricated-steel engine construction.](#)
- [29. The 'Nikasil' process.](#)
- [31. Castor-base oil.](#)
- [32. 1923 Sunbeam: Exhaust valve condition post-French Grand Prix.](#)
- [36. Dimensions as designed and as cast.](#)
- [40. The Bugatti change of cylinder head, 1931.](#)
- [44B. Mercedes and Auto Union \(Bore/Cylinder-centres\) ratio, 1934 – 1937.](#)
- [48. "Super-Tuning" with short life.](#)
- [52. Fuel Injection.](#)
- [55. Maserati 250F Head Sealing.](#)
- [57. Squish in Maserati 250F?](#)
- [69. Oil Scavenging.](#)
- [71. Low pressure crankshafts.](#)
- [71B. Cylinder liners in compression.](#)
- [78. The four valves-per-cylinder revival, 1959 onwards.](#)
- [81. Ford-Cosworth big-end journal diameters.](#)
- [82. Mercedes-Benz/Bosch experiments with RPM governor.](#)
- [87. The new Cosworth Al-alloy casting process.](#)
- [88B. 90° shift of major axis on connecting rods.](#)
- [103. "Diamond-Like-Carbon" \(DLC\) surface treatment.](#)
- [107. Probable Inlet Valve Diameter \(IVD\) for some recent 4 v/c engines.](#)